

PUN 25 – 47

17-September, 2025

Honeywell Announces Updates to the Granit™ Ultra Cordless 2105i SR and XR Ultra-Rugged Handheld Scanners

Honeywell is announcing a firmware update for Granit Ultra cordless 2105i SR and XR scanners.

Honeywell has discovered that, in certain limited circumstances, when the battery state of charge is depleted to a very low level, it may not be charged by the Charge and Communication Base (CCB23), which would prevent the 2105i scanner from powering up. Upgrading to the new scanner firmware will resolve this issue.



Granit Ultra 2105i Scanner

The new firmware is available on the Honeywell Support Software and Downloads Portal [HERE](#) and can be installed via standard software tools.

- 2105i SR Scanner Firmware: HK000070BAA
- 2105i XR Scanner Firmware: HL000073BAA

Granit Ultra 2105i products with serial numbers ranging from SN **25014Bxxxx** to SN **25244Bxxxx** are recommended for upgrade.

NEW PART NUMBERS

All Granit Ultra 2105i SR and XR SKUs are affected by this notice.

ABOUT THE GRANIT ULTRA

For a scanner to optimize productivity, it should read and transmit common barcodes nearly as fast as the user can pull the trigger, and Granit Ultra is engineered to do just that. Granit Ultra integrates high-speed processing, AI algorithms, and decoding enhancements to result in an average 45% scanning speed increase vs. Granit XP*, enabling improved productivity.

Granit Ultra-Rugged Handheld Scanners are ready to deliver productivity results in environments where harsh treatment would render lesser scanners unreliable. 10' drops from fork trucks, docks, and picking trucks, 7,500 tumbles from 3'/1m (typical working height), and wide operating temperatures from deep freezers to summer heat are no problem.

*Honeywell standard benchmarking testing conducted on Granit Ultra SR and XR models vs. Granit XP on 6 collections of reference barcodes

**Honeywell Industrial
Automation**
855 S Mint St
Charlotte, NC 28202
800-582-4263
automation.honeywell.com

The SR model is designed for arms-length barcode reading, while the XR model dramatically expands the read range to nearly 6' (1.8m) for UPC or 36' (10.85m) for 100 mil Code 39 symbols.

For additional information, please visit the Granit Ultra 2105i Scanner product page [HERE](#).

REGIONS AFFECTED

- | | |
|--|--|
| ☒ Asia Pacific (APAC) | ☒ Middle East, Turkey, Africa (META) |
| ☒ Europe (EU) | ☒ Latin America (LATAM) |
| ☒ Greater China (GrCH) | ☒ North America (NA) |

KEY DOCUMENT LINKS

- [Granit Ultra 2105i Product Webpage](#)

TIMELINE OF EVENTS

ANNOUNCEMENT	DATE
First Order Date	Immediately
First Ship Date	17-September, 2025
Standard Lead Time	Consult your Honeywell Representative

PROTECT YOUR INVESTMENT

With Honeywell Repair Services, it's easy to get the level of repair coverage and protection that makes the most sense for your business. Honeywell repair service programs not only protect your device investment, but also provide predictable repair costs for the duration of your agreement. In addition to repairs, with every depot service we also provide required preventative maintenance, as well as relevant engineering, software, and firmware updates.

FOR MORE INFORMATION

Honeywell is committed to providing you with a superior level of customer service. Please contact your Honeywell representative for additional information regarding this communication.

Granit is a trademark or registered trademark of Honeywell International Inc. in the United States and/or other countries.