

PUN 24 – 23

19-July, 2024

Honeywell Announces Firmware Update for PM45, PX940, PX240/PD45 and PC42 Printers

Honeywell is pleased to announce the latest maintenance release firmware for PM45, PX940, PX240/PD45, and PC42 printers. The latest firmware version is MR20.6, which addresses miscellaneous field issues and provides updated cybersecurity enhancements. MR20.6 is currently available on the Honeywell firmware download page, and will be installed on new printers in production beginning 10-July, 2024. Previous firmware versions (maintenance releases and field trials) will be removed from the Honeywell firmware download site.

NEW PART NUMBERS

See the Excel table for a list of the new SKUs / SKUs affected by this notice.



REGIONS AFFECTED

- | | |
|--|--|
| ☒ Asia Pacific (APAC) | ☒ Middle East, Turkey, Africa (META) |
| ☒ Europe (EU) | ☒ Latin America (LATAM) |
| ☒ Greater China (GrCH) | ☒ North America (NA) |

PROTECT YOUR INVESTMENT

With Honeywell Repair Services, it's easy to get the level of repair coverage and protection that makes the most sense for your business. Honeywell repair service programs not only protect your device investment, but also provide predictable repair costs for the duration of your agreement. In addition to repairs, with every depot service we also provide required preventative maintenance, as well as relevant engineering, software, and firmware updates.

FOR MORE INFORMATION

Honeywell is committed to providing you with a superior level of customer service. Please contact your Honeywell representative for additional information regarding this communication.